



1/13
FIG.1



2/13
FIG.2



3/13

FIG.3




FIG.4





FIG.5

AXIS DEVIATION RELATIVE TO OBJECTIVE LENS EXCEED TOLERANCE
LEVEL. DO YOU EXECUTE AXIS ALIGNMENT ?

Yes

No

6/13
FIG.6



7/13

FIG.7




FIG.8 (a)




FIG.8 (b)






FIG.9




10/13

FIG.10



11/13
FIG.11



12/13
FIG.12

(500)

(501)	<input checked="" type="checkbox"/>	Auto Focus
(502)	<input checked="" type="checkbox"/>	Alignment Pattern
(503)	<input type="checkbox"/>	Wafer Pattern
<hr/>		
(504)	Axis	<input type="text" value="1000000"/> <input type="text" value="1000000"/>
(505)	Mag.	<input type="text" value="x100k"/> (30k~100k)
(506)	Frame	<input type="text" value="16"/>
<hr/>		
(511a)	Auto Axis Alignment Mode	<input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3
<hr/>		
(507)	<input checked="" type="checkbox"/>	Auto Stigma Alignment X
(508)	<input checked="" type="checkbox"/>	Auto Stigma Alignment Y
(509)	<input checked="" type="checkbox"/>	Auto Axis Alignment
<hr/>		
(510)	<input checked="" type="checkbox"/>	Auto Stigma
<hr/>		
		<input type="button" value="OK"/>

FIG.13

